









Assembly Instructions


9904







60 min







		9904
1	1	440x330x18MM
2	1	440x330x18MM
3A	1	328x204x18MM
3B	1	328x204x18MM
4	1	214x412x5MM
5	2	398x99x18MM
6A	2	250x80x15MM
6B	2	250x80x15MM
7	2	243x361x5MM
8	2	350x80x15MM







 ϕ 15x12 AX16	 M6x35 BX16	 ϕ 8x40 CX8	 M3. 5x15 DX20
 250mm EX4	 3. 5x40 FX8	 M8x40 GX8	 ϕ 18xM8x1. 2 HX8
 M8 IX8	 M6x40 JX6	 ϕ 12x1xM6 KX6	 5# LX 1
 350x50x30 MX4	 NX2	 OX2	 PX8
 QX1	 RX4		





1





E=E1+E2




2



3




4




5



Ax4



6




8-13

7



Bx4

Cx4



8

Ax4




9-13


9



DX8




E2x4



10




BX4




10-13

11




12



13



PX8



14



Ax8



FX8



DX8




NX2



OX2



E1




15



DX4



RX4



14

